

# Action Tape 4004 COATING 60

#### Product Information 01.2020

1/2

#### **Action Tape 4004**

This product is a double sided acrylic based adhesive tape, which is especially designed for a wide variety of materials with low surface energy. The tape is capable of absorbing the differing thermal expansions of the two different materials. This modified multipurpose adhesive tape is suitable for (powder)coatings and several plastics with low energy surfaces (LSE) and has been specifically developed for applications where the use of a primer or adhesion promoter is not preferred. High performance tapes from the 1000 series have an excellent initial tack and adhesion during the application of powder coated surfaces, plastics, coated glass and other low surface energy surfaces. Other features include good plasticizer resistance and very good adaptability.



90° Peel Adhesion	N/10mm (lb/in)	40 (2)	2)	ASTM D3330
Dynamic Shear Strength	kPa (lb/in²)	650 (9	(4)	ASTM D-1002
Normal Tensile	kPa (lb/in²)	650 (94)		ASTM D-897
Static Shear Strength	Grams Weight that ½ square inch will hold for 10,000 minutes (7 days)	22°C (72°F) 66°C (150°F) 93°C (200°F) 121°C (250°F) 177°C (350°F)	1000 500 500 250	ASTM 3654

#### Suitable for:

- several LSE surfaces like, powder coatings, plastics, coated glass, ceramics, silicones, teflon, PP, PE \* Available sizes:

- jumbo: 900mm x 330 meters (core 3")
- log: 900mm x 33/66 meters (core 3")
- slit roll: 4 250mm x 33/66 meters (core 3")
- spool roll: 5 25mm x max 900 meters (core 6")



# Action Tape 4004 COATING 60

Product Information 01.2020

2/2

## Application Guidelines

Every good bond starts with proper surface preparation. This preparation consists of several steps, such as cleaning, abrading, applying pressure, the use of a primer and the right working environment. It is important to ensure your work area to beclean and free from dust and contaminants.

A minimum temperature of 15 °Celsius is required.

### Cleaning

To clean your light and medium contaminated substrates, CCP recommends an isopropanol/alcohol solution (IPA). When cleaning your substrate, a tear free, light colored paper towel is required. Wipe the substrate in one direction using the one cloth method (one cloth with cleaner) or a two cloth method (one cloth with cleaner and one dry cloth to follow) is acceptable if you are short on time. Repeat these steps until your cloth is clean and free of any contaminants. For heavily contaminated substrates, use a cleaning agent such as MEK, Heptan or Acetone. These cleaning agents may leave a residue. which would have to be removed using the IPA cleaner.

#### **Abrasion**

When bonding to raw aluminum, abrading of the surface is a must. The oils used in the waltzing of the aluminum are pressed into the pores of the material. To remove these oils, that will influence the bond, we recommend using abrasive pads to ensure the proper level of abrasion without damaging your substrates. Besides raw aluminum, abrading is a method utilized to help improve your bond. After the abrasion process is completed, remove any residue using an IPA cleaner following the methods mentioned above.

#### Primer

The use of a primer is recommended when bonding to some low surface energy substrates. Examples include, different types of polymers, powder coated metals, or porous materials such as wood, cork, stone or concrete. Primers are also used to help speed up your production process. The CCP Action Tape line can take up to 72 hours to reach its end-strength. The use of a primer ensures the end-strength will be achieved within 20 minutes. Your CCP technical support will gladly advise you which primer to use.

#### **Pressure**

CCP Action Tapes are pressure sensitive adhesives. Therefore,a minimum amount of pressure is required on the bond line to ensure the maximum adhesion to your substrates. This pressure should be applied in a rolling fashion. A hand roller or mechanical presser are the preferred methods. The pressure on the bond line must be a minimum of at least 10N/cm<sup>2</sup>.

## Storage & Shelf life

Please make sure that the tape is stored in its original packaging, in a dry place and at a preferable temperature between 4 °C and 38 °Celsius. When the tape is stored under the proper conditions, the tape has a shelf life of 18 months.

### \*Important Information

All technical data in this product data sheet are based on CCP's experience and external testing institutes. These values are representative of the overall performance. These data sheets are NOT to be used for specification purposes or for your own specific application. It is your responsibility to test whether the tape is suitable for your application or project. CCP will NOT be held liable for any information provided on this

You must follow the rules and regulations that are applicable in the state, county or country where the CCP product(s) are being used. If you have any questions regarding the use of the CCP Action Tape acrylic foam tapes, please contact our technical sales team. For questions on the standard warranty, please review our standard delivery terms and conditions. For all other warranties, please review all documents that should have been agreed to in writing prior to the sale between CCP and the customer. Action Tape is a brand name of CCP.